

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) (EP 1130-2-520)						PAGE 1 OF PAGES 1		
						DATE 6 August 2008		
TO: Navigation Interests					FROM: U.S. Army Engineer District, Baltimore P.O. Box 1715 Baltimore, Maryland 21203-1715			
RIVER/HARBOR NAME AND STATE Baltimore Harbor Baltimore, Maryland					MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD			
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Inner Harbor	19 May 2008				10	18	22	10
REMARKS (Continue on reverse) All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. LQ=E1424192.99, N587882.99 (10.1') LIQ=E1426512.95, N586407.71 (18.1') RIQ=E1424753.04, N588007.79 (22.3') RQ=E1424833.03, N588123.88 (10.2')								